

PICnMIX MECHANICAL DRAWING

This is an actual print of the centres of the holes and LED positions for the PICnMIX PCB.

There are some extra lines on this drawing which should not be confused with those holes you need to drill. You can use this drawing for mounting this PCB and for making a front panel, to allow the LED's to pass through etc.

Not all mounting holes need be used. It is up to you which ones you use but normally, two holes at each end of the main PCB plus one adjacent to the keypad should be sufficient.

Please double check before you drill any holes !!

Please check the scaling of this printout. The pdf print should be set up for NO scaling of the print. This print was made for A4 size paper.

Glenn



